

GENUINE GRACO PARTS AND ACCESSORIES




243155 Cylinder Seal Repair Kit

For TRITON[®] 1030HP Double Diaphragm Pump



Read warnings and instructions.
Refer to manual 309476.

406551B



- △1 Lubricate.
- △2 Torque to 8 N•m (5.9 ft-lb)
- △3 Torque to 15 N•m (11 ft-lb)
- △4 Torque to 6 N•m (4.4 ft-lb)
- △5 Torque to 20 N•m (15 ft-lb)
- △6 Torque to 10 N•m (7.4 ft-lb)

Graco Inc. P.O. Box 1441 Minneapolis, MN 55440-1441
406551 Rev. B 08/2003 Printed in USA
Copyright 2002, Graco Inc. is registered to I.S. EN ISO 9001

ti2074a