

GENUINE GRACO PARTS AND ACCESSORIES




243154 Check Valve Repair Kit

For TRITON[®] 1030HP Double Diaphragm Pump



Read warnings and instructions.
Refer to manual 309476.

406550B



Torque to 10 N•m (7.4 ft-lb)

Graco Inc. P.O. Box 1441 Minneapolis, MN 55440-1441
406550 Rev. B 08/2003 Printed in USA
Copyright 2002, Graco Inc. is registered to I.S. EN ISO 9001

ti1960a

