

245066 Air Valve Kit

Kit de réparation pour vanne d'air/Kit de reparación de la válvula de aire/
 Kit de reparação da válvula de ar/Luftventil-Reparatursatz/
 Reparatieset voor luchtventiel/Reservdelssats luftventil/
 Kit di riparazione della valvola aria/ 空氣閥門修理包 / エアバルブ修理キット / 공기 밸브 보수 키트

406509G

ENG

TRITON® 308 & TRITON® 308HP



Important Safety Instructions

Read all warnings and instructions in manuals
 309303 (Triton 308) and 309479 (Triton 308HP).
 Save all instructions.


1 308: 7.3 ft-lb (10 N•m); 308HP: 8.8 ft-lb (12 N•m)

2 Lubricate

3 Align

4 28 in-lb (3.1 N•m)

5 Orient "POM" marking on air valve plate as shown in relation to fluid outlet arrow.



TRITON 308 SHOWN

GRACO INC. / P.O. BOX 1441 / MINNEAPOLIS, MN 55440-1441

406509 Rev G 01/2010

Original instructions. MM 406509

Copyright 2010, Graco Inc. is registered to ISO 9001