

GENUINE GRACO PARTS AND ACCESSORIES



235635 Repair Kit

For Model 223587 and 223842
Severe-Duty Displacement Pump

406136F




Important Safety Instructions

For detailed service instructions and warnings, see manuals 306981 (pump 223587) or 308106 (pump 223842).

Ref. Part	Description	Qty.
1	105444 BALL, bearing, 5/16 in.	1
2	105445 BALL, bearing, 1/2 in.	1
3	164477 PACKING, leather	6
4	164862 PACKING, PTFE	6
5	165052 O-RING	1
6	186182 GLAND, male	2
7	186181 GLAND, female	2
9	164480 GASKET, PTFE	1


Throat packing arrangement for 223587

Throat packing arrangement for 223842



Piston packing arrangement for 223842

Piston packing arrangement for 223842



Lips of **throat** packings must **face down**. Lubricate packings.

Lips of **piston** packings must **face up**. Lubricate packings.

02506

Graco Inc. P.O. Box 1441 Minneapolis, MN 55440-1441

406136 Rev F 2/2011

Copyright 1993, Graco Inc. is registered to I.S. EN ISO 9001